Inspection Report

Name of Work	: Construction of Rainwater Harvesting Structure and Recharging Pits in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.
Work Order	: EE/BTP/BBMP/E-PMT-07(13874)/WO/183/2014-15 Dated: 07.01.2015.
Agency	: Mohan Kumar. V
B.R. No & Date	: 477/2014-15 Dated: 28.02.2015
Bill Amount	: 14,98,663.56
Job Code	: 011-15-000010
P. Code	: P-1771
Date of Inspection	: 16-02-2016.

The above said work Construction of Rain water harvesting structure and Recharging pits in ward no 11 (Kuvempunagara) Vidyaranyapura Sub Div. was Shown to me by the Concerned A.E.

The above said works at different location were inspected by me along with Concerned AE Sri Rangaraju and verified the photos which were taken during Execution. and found Satisfactory. The work done is Satisfactory

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Sketch for the Work of Construction of Rainwater Harvesting Structure and Recharging Pits in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.



'verified'

- Recharging Pits

Junior Engineer
Ward No. 11

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

...s for the Work of Construction of Rain Water Harvesting Structure and Recharging Pits in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

...s for the Work of Construction of Rain Water Harvesting Structure and Recharging Pits in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

...os for the Work of Construction of Rain Water Harvesting Structure and Recharging Pits in Ward No. 11 (Kuvempunagara) Vidyaranyapura Sub Division.



MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT